



WIPE NEW® HEADLIGHT RESTORE KIT

DESCRIPTION AND USES

Rust-Oleum® Wipe New® Headlight Restore is a long-lasting solution that restores clarity to aging and fogging headlights.

FEATURES

- Restores illumination and visibility
- Easy-to-use, wipe on solution
- Long lasting shine - Protects through 100 car washes

PRODUCT

SKU	DESCRIPTION
335789	Wipe New Headlight Restore Kit

PRODUCT APPLICATION

APPLICATION CONDITIONS

Use when temperatures are between 4°C and 32°C. Use in well ventilated and covered areas away from the sun. Do not apply Headlight Restore to hot surfaces or in direct sunlight. Ensure surface is clean, dry and cool to ambient temperature before applying Headlight Restore.

SURFACE PREPARATION

Prep the exterior of all lenses intended for application at the same time so that one Wipe-It™ can be used to treat all lenses. Once the Wipe-It is opened it begins to cure. Do NOT open the Wipe-It until needed and complete the application within a few minutes.

Wash the intended surface thoroughly with a standard soap, cleaner or car wash (free of wax, moisturizers or other additives). Rinse and let dry. For best results, apply a degreaser to heavily worn areas to fully clean the surface.

To determine whether you need to use the Professional Lens Polishing Pad, pour water onto your headlight lens. The way the lens looks when wet is the way it will appear once treated with Headlight Restore. If the lens appears crystal clear when wet (and hazy only when dry), then you do not need to use the Lens Polishing Pad. Simply wash the lens with soap and water, rinse, let dry completely and apply Headlight Restore. If the lens appears cloudy or hazy when wet; the Lens Polishing Pad will be required.

Wet the headlight lens with water and use the green side of the Lens Polishing Pad to wet sand the headlight lens and remove oxidation. Ensure the lens remains wet while using the Polishing Pad. The oxidation coming off the lens will appear as a brownish colored liquid; continue to rub until this visual indicator is no longer present.

IMPORTANT: Do not allow the Polishing Pad to come into contact with painted surfaces as it may scratch these surfaces.

PRODUCT APPLICATION (cont.)

SURFACE PREPARATION (cont.)

Re-wet the headlight lens and use the gray side of the Professional Lens Polishing Pad to further polish the headlight lens.

Dry the lens thoroughly with the included microfibre towel and inspect the surface to ensure oxidation has been removed. If not, repeat steps above on any missed spots. When you can see through the lens while wet, you are ready to apply Wipe New. Ensure all lenses are 100% dry prior to proceeding to application.

APPLICATION

Put on the chemical resistant gloves and ensure that you are in a well ventilated area. Make sure headlight lenses are completely dry. Tear open the Wipe-It packet, pull out the applicator cloth and carefully wipe the lens **ONE TIME** in a single wipe, from one row to the next, with a slight overlap (like mowing a lawn) until the surface is completely coated. Be careful to not get any Wipe New on the surrounding paint. If treating multiple lenses, do so before the Wipe-It dries out. If Wipe New comes in contact with an unintended surface such as paint; wipe it off immediately with a dry cloth. Within an hour of application (while still undergoing initial cure), acetone may be used to remove Wipe New from a painted surface, but not from plastic or any nonmetal surface. Because acetone can damage vehicle parts or paint, it should be used only after checking with the vehicle manufacturer or a Certified Paint Professional as to how to best apply or remove product. After Wipe New has cured, removing it will require the use of a fine polishing compound or high grit automotive sandpaper.

DRY TIME

The headlights will dry to the touch in about 1 hour. Do NOT allow treated lenses to come in contact with direct moisture (rain, dew, etc.) for 24 hours. Store excess product in a cool, dry place.

COVERAGE

One Wipe-It contains enough Wipe New to treat the exterior of multiple headlight lenses.

DISPOSAL

When finished, set the applicator cloth in a location out of the reach of children and allow it to dry completely prior to discarding (a few hours).

	TECHNICAL DATA	WNW-19
	WIPE NEW® HEADLIGHT RESTORE KIT	

PHYSICAL PROPERTIES

WIPE NEW HEADLIGHT RESTORE KIT		
Resin Type	Siloxane Polymer	
Pigment Type	NA	
Solvents	N-Butyl Acetate, Parachlorobenzotrifluoride	
Volatile Organic Compounds	None	
Practical Coverage	Contains enough to treat the exterior of multiple headlight lenses	
Dry Times at 21-27°C and 50% Relative Humidity	Touch	1 hour
	Recoat	NA
	Full Cure	24 hours
Shelf Life	5 years	
Flash Point	37°C	
Safety Information	For additional information, see SDS	

The technical data and suggestions for use contained herein are correct to the best of our knowledge, and offered in good faith. The statements of this literature do not constitute a warranty, express, or implied, as to the performance of these products. As conditions and use of our materials are beyond our control, we can guarantee these products only to conform to our standards of quality, and our liability, if any, will be limited to replacement of defective materials. All technical information is subject to change without notice.



Rust-Oleum Australia PTY. LTD.
Unit 12, 4 Southridge Street
Eastern Creek, NSW 2766 Australia
PH: 1 300 784 476
www.rustoleum.com.au
email: sales@rustoleum.com.au

HAYDN BRUSH CO. LTD.
PO Box 86054
Christchurch, 7675 New Zealand
PH: 64 3 347 7770
www.rustoleum.co.nz
Email: info@haydn.co.nz

Form: ARJ-1454
Rev.: 121117